

**SPX****POWER TEAM®**

SPX Corporation  
5885 11th Street  
Rockford, IL 61109-3699 USA

Tech. Services: (800) 477-8326  
Fax: (800) 765-8326  
Order Entry: (800) 541-1418  
Fax: (800) 288-7031

Internet Address:  
<http://www.powerteam.com>

Form No. 100631


## Parts List for:

5RLS100S  
100201  
421658  
RLS100

RLS100-GLFP  
RLS100-KAW  
RLS100-PFAFF

**SINGLE-ACTING, SPRING RETURN  
HYDRAULIC CYLINDER**

**Max. Capacity: 5.6 Tons at 5,000 PSI**  
**11.2 Tons at 10,000 PSI**



Sheet No. 1 of 1

Rev. 5

Date: 28 Oct. 1998

# Parts List, Form No. 100631, Back sheet 1 of 1

Item No.	Part No.	No. Req'd	Description
1	*15088	1	Rod Wiper
2	46203	1	Retainer (Torque to 300/350 in. lbs.)
3	212044	1	Compression Spring (For all models except RLS100-GLFP)
4	46205	1	Piston (For all models except 421658 & RLS100-GLFP)
	421659	1	Piston (For 421658)
	421742	1	Piston (For RLS100-GLFP)
5	*19272	1	Backup Washer
6	*14739	1	O-ring (1-11/16 X 1-1/2 X 3/32)
7	46206	1	Cylinder Body
8	9796	1	Cylinder Half Coupler w/Dust Cap (For RLS100, RLS100-PFAFF & RLS100-GLFP)
	210916	1	Coupler (For 5RLS100S)
	250365	1	Coupler (For RLS100-KAW)
9	10676	1	Straight Fitting (For 100201)
10	9790	1	Dust Cap (For RLS100-KAW)

## PARTS INCLUDED BUT NOT SHOWN

16473	1	Patent Decal
*203908	1	Warning Decal (For 100201 & 421658)
212064	1	Warning Decal (For RLS100, RLS100-KAW & RLS100-GLFP)
351911	1	Trade Name Decal (For RLS100)
212355	1	Trade Name Decal (For 5RLS100S)
215829	1	Trade Name Decal (For 100201 & 421658)
251931	1	Trade Name Decal (For RLS100-PFAFF)
212064-CE	1	Warning Decal (For RLS100-PFAFF)
252182	1	Decal (For RLS100-PFAFF)

Part numbers marked with an asterisk (\*) are contained in Repair Kit No. 300455.

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine Power Team replacement parts!**

Additional questions can be directed to our Technical Services Department.

Note: Shaded areas reflect last revision(s) made to this form.