


MODEL C
DOUBLE-ACTING, HOLLOW CENTER
HYDRAULIC CYLINDER
Max. Capacity: 61.5 Tons at 10,000 PSI



Double-acting
Cylinder
Relief Valve

See important
! DANGER
statement
on back of
sheet 1 of 1



DANGER: To help avoid possible serious personal injury or death,

- In the event that the cylinder retract port is ever restricted or plugged, a double-acting cylinder relief valve will help prevent excessive pressure from building in the cylinder. **DO NOT** attempt to adjust or service this relief valve! If oil leakage is detected from this relief valve, discontinue use of the cylinder immediately and contact Power Team Technical Services. Only Power Team Authorized Hydraulic Service Centers should service this relief valve.

Item No.	Part No.	No. Req'd	Description
1	9697	2	Coupler, Quick Cylinder Half
2	*14336	1	O-ring (5.25 x 5.00 Urethane)
	104576	1	O-ring (5.25 x 5.00 Viton)
3	*206807	1	Washer, Backup (5.25 x 5.00)
4	*28821	1	U-cup (4.38 x 4.00 x .19 H)
	206142	1	U-cup (Wiper, Strip Viton)
5	41442	1	Nut, Gland (5-1/4-12)
6	350002	1	Insert, Plain
7	*14333	1	U-cup (3.00 x 2.63 x .38 H)
	206145	1	U-cup (3.00 x 2.63 x .38 H)
8	*19042	1	O-ring (2.87 x 2.62 Viton)
9	351584	1	Standpipe
10	251482	1	Screw, Set (10-24 x 1/4)
11	*14334	1	T-seal (4.75 x 4.38 x .27 L)
	19245	1	T-seal (4.75 x 4.38 x .27 L)
12	*207721	1	Wiper, Rod (3.00 x 2.63 Urethane)
	206123	1	Wiper, Rod (3.00 x 2.63 Viton)
13	65717	1	Body, Cylinder (For RH605N)
	65716	1	Body, Cylinder (For RH605 & RH605-PFAFF)
14	41440	1	Piston
15	*14335	1	U-cup (4.38 x 4.00 x .38 H)
	206146	1	U-cup (4.38 x 4.00 x .38 H)
16	421613OR9	1	Handle, Cylinder Lift (For RH605 & RH605N)
	421613BL6	1	Handle, Cylinder Lift (For RH605-PFAFF)

PARTS INCLUDED BUT NOT SHOWN

*203908	1	Decal, Warning (For RH605 & RH605N)
*203908-CE	1	Decal, Warning (For RH605-PFAFF)
351580	1	Decal, Tradename Power Team (For RH605 & RH605N)
252186	1	Decal, Tradename Power Team (For RH605-PFAFF)
19526	2	O-ring (1.00 x .75 Viton; For Coupler)
205724	1	Decal, Attention (Viton Seals)

Part numbers marked with an asterisk (*) are contained in Standard Repair Kit No. 300269.

Part numbers marked with a double dagger () are contained in Viton Seal Kit No. 300226.



Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine Power Team replacement parts!**

Additional questions can be directed to our Technical Services Department.